2 October 1967

MEMORANUDM FOR THE RECORD

SUBJECT: BX6724 Automated Flight Plan

- 1. During BX6724 an unusual amount of time was utilized before receipt of the flight plan with options.
 - 2. The problems that created this time consumption are as listed:
 - A. Computer Machine
 - (1) Software disks etc.
 - (2) Hardware 360/7090 Emulation
 - B. Operator OSA and OCS
 - C. Flight Planners
- 3. Each of these factors contributed to the late transmission of both the primary route and option route.
- 4. Steps are being taken to alleviate the recurrence of delays on future missions. The necessary coordination/requirements have been accomplished.

25X1

25X1

